

Machine Shop Warning!

Moving parts on shop equipment can cause serious injury or death! Flying chips, sparks, and other particles may cause serious injury!

- Always receive proper training before operating machinery. Do not use a machine if you are not familiar with it.
- Access after hours is prohibited, unless previously cleared by a Supervisor.
- Do not work alone.
- Secure loose hair, clothing, ID badges and jewelry (watches, rings, bracelets, etc.) before operating any machinery.
- Always wear proper PPE. Appropriate eye protection is required before use of any machinery.
- No open toed shoes.
- Never remove shield or machine guards.
- Keep hands and body clear when operating machinery. Maintain a safe distance.
- Avoid distraction. This includes the use of headphones, earbuds, or mp3 devices.
- No eating in the shop area.
- Never operate machinery when impaired. This includes but is not limited to being under the influence of drugs or alcohol, being ill, or being sleep deprived.
- Clean up after yourself
- Report any damaged or malfunctioning equipment immediately.

